

Chippinghouse Road

N

Steade Road




Side of 81 Steade Rd, at end of St Ronans rd o/s 36

o/s 20

o/s 10

St Ronan's Road

o/s 35 o/s 31



© Crown copyright and database rights 2016 Ordnance Survey 100018816

Scale: 1:500

Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
o/s 31	ST RONAN'S ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 31 (same as felled tree)	434688.21	385171.3	Tilia americana 'Redmond'	434688.21	385171.33
o/s 20	ST RONAN'S ROAD	Fraxinus excelsior	Damage to Surface	Damaging	TR: Replanting, Tilia 'Redmond' - Plant in new 800mm pit o/s 20 (same as felled tree)	434735.59	385178.67	Tilia americana 'Redmond'	434735.61	385178.58
o/s 36	ST RONAN'S ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Acer 'Louisa Red Shine' - Plant in new 800mm pit o/s 36 (same as felled tree)	434658.47	385178.59	Acer campestre 'Louisa Red Shi	434658.23	385178.93
o/s 35	ST RONAN'S ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Acer 'Louisa Red Shine' - Plant in new 800mm pit o/s 35 (same as felled tree)	434676.18	385171.3	Acer campestre 'Louisa Red Shi	434676.45	385171.47
o/s 10	ST RONAN'S ROAD	Acer pseudoplatanus	Damage to Surface	Damaging	TR: Replanting, Acer 'Louisa Red Shine' - Plant in new 800mm pit o/s 10 (same as felled tree)	434786.6	385178.67	Acer campestre 'Louisa Red Shi	434786.98	385178.99
Side of 81 Steade Rd, at end of St Ronans rd	ST RONAN'S ROAD	Fraxinus excelsior	Structural Integrity	Dangerous	TR: Replanting- Tilia 'Redmond' - Side of 81 Stead Rd, at end of St Ronans Rd, (same as felled tree)	434644.23	385179.1	Tilia americana 'Redmond'	434643.41	385178.28